

PATRICK C. GARNER CO., INC.
Northborough, Massachusetts

PROJECT SHEET:

**Charles River Bank Restoration Following 2010 MWRA Water Line Failure,
Weston, Massachusetts**



In 2010 the Town of Weston retained Patrick C. Garner Co., Inc., to monitor and supervise the fast-tracked bank restoration of a portion of the Charles River. In May 2010 a section of MWRA water main supplying Boston blew out, sheering off several hundred feet of embankment along the river.

Garner worked closely with the Town's Conservation Commission, MassDEP, MWRA and contractors to ensure that work was completed on schedule using optimal riverine techniques. On-site modifications were required and

Garner's restoration recommendations were incorporated in the site changes. Garner conducted the work during June of 2010.

The project was successfully completed and stands as an excellent contemporary example of river bank restoration in the Commonwealth.